




2024-25

## SAFETY CERTIFICATE

The building of Maharishi Vidya Mandir Senior Secondary School Khatehar P.O. Dhagwar, in Tehsil Dharmshala Distt. Kangra H.P. was inspected by the concerned Junior Engineer. As per the report of Junior Engineer this building has neither been designed nor been constructed by this office. No earthquake resistant norms have been adopted for this building. No structural drawings approved by the competent Govt. agency have been produced. The structure is a Non-Engineered Structure. Hence the structural safety of this building cannot be ensured specifically from earthquake point of view. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe at present only. This certificate is valid for academic session for 2024-25.

  
Junior Engineer  
HP.PWD Sub Division .II  
Dharmshala .

  
Assistant Engineer,  
HPPWD Sub Division. II  
Dharmshala.

  
Executive Engineer  
Dharmshala Division  
HPPWD Dharmshala

Place: Dharamshala  
Dated:


No. PW/DD/CB/WAB/B-17/2018-19

Himachal Pradesh  
Public Works Department  
13543-44

Dated: 27-1-2024

✓ Copy forwarded to the Principal, Maharishi Vidya Mandir, Khatehar, Dhagwar, Tehsil Dharamshala, Distt. Kangra, (H.P.) for information with reference to his application No. MVM/Daramshala/387/2023 dated 28-12-2023 please.

Copy forwarded to the Assistant Engineer, Dharamshala Sub-Division No. II, HPPWD, Dharamshala for information with reference to his office letter No. 1418 dated 16/01/2024.

  
Executive Engineer,  
Dharamshala Division,  
HPPWD, Dharamshala