




SAFETY CERTIFICATE

The school building of Maharishi Vidya Mandir Senior Secondary School village Khatehar Post office Dhagwar Tehsil Dharmshala Distt Kangra H.P. was inspected by the concerned Junior Engineer. As per the report of Junior Engineer the buildings has neither been designed nor been constructed by his office. No earthquake resistant norms have been adopted for this building. No structural drawing approved by the competent Govt. agency have been produced. The structure is Non-Engineered Structure. Hence the structural safety of this building cannot be ensured specifically from earthquake point of view. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe at present only. This certificate is valid for academic session for 2020-21.


Junior Engineer
HP.PWD Sub Division. II
Dharmshala


Assistant Engineer,
HPPWD Sub Division. II
Dharmshala.


Executive Engineer
Dharmshala Division
HPPWD Dharmshala

Place: Dharamshala
Dated:

NO.PW/DD/CE/WAB/B-17/2020

Himachal Pradesh
Public Works Department

4798-99

Dated:- 15-10-2020

Copy forwarded to the Principal, Maharishi Vidya Mandir Sr. Sec. School Khatehar Dhagwar Dharamshala Tehsil Dharamshala, Distt. Kangra (HP) for information with reference to his application No. MVM/Dharamshala/2020 dated 30/07/2020 please.

Copy forwarded to the Assistant Engineer, Dharamshala Sub-Division No.II, HPPWD, Dharamshala for information with reference to his office letter No. 6082 dated 07/10/2020.


Executive Engineer,
Dharamshala Division,
HPPWD, Dharamshala


Principal
Maharishi Vidya Mandir
Khatehar Dhagwar Dharamshala
Distt. Kangra Pin Code - 176001